



Sharing on Safe Management Measures at Senja 12 Storey Integrated Development

Anthony Saviour

WSHO

27 Jul 2020

AGENDA

- PROJECT INTRODUCTION
- SAFE WORKFORCE
- SAFE WORKSITE
- SAFE ACCOMMODATION
- SAFE TRANSPORTATION
- FIT-OUT YARD GRADUAL RE-START
- CONCLUSION

PROJECT INTRODUCTION

This is a design & build project for new 12-Storey Integrated Development.



| | | |
|----------------|---|------------------------|
| Site Area | : | 5,360.8m ² |
| GFA: | : | 20,559.0m ² |
| AMSL | : | 62.62 AMSL |
| No. of Storeys | : | 12 Storeys |

SAFE WORKFORCE

IDENTIFICATION OF CONTRACTORS

| Summary of Subcontractors' Workers Staying at DORMITORY UNDER ISOLATION & COVID-19 CLUSTERS | | | | | | | | |
|---|---|--------------------|---|--------------------|-----------------------------|--------------------|--------------|------------|
| S/N | Subcontractors | Numbers of Workers | Dormitory Name/ Address | Types of Dormitory | Status of Dormitory (CL/NC) | COVID-19 | | Remarks |
| | | | | | | Negative/P ositive | No. of Cases | |
| Structural Works | | | | | | | | |
| 1 | Jia Yue Construction Pte Ltd | 26 | Sungei Tengah Lodge, 500 Old Choa Chu Kang Road | PBD | NC | Negative | | |
| | | 3 | Tuas View Dormitory, 70 Tuas South Avenue 1 | PBD | CL | Negative | | |
| | | 2 | Kranji Lodge 1, 12 Kranji Rd | PBD | NC | Negative | | |
| 2 | Yang Peng Engineering Pte Ltd | 17 | Sungei Tengah Lodge, 500 Old Choa Chu Kang Road | PBD | NC | Negative | | |
| 3 | Tianming Construction | 6 | Eng Lee Dormitory, 12 Kian Teck Crescent | PBD | NC | Negative | | |
| | | 4 | CDPL Tuas Dormitory, 6 Tuas South Street 15 | PBD | CL | Negative | | |
| 4 | Xinguohe Construction | 6 | Sungei Tengah Lodge, 500 Old Choa Chu Kang Road | PBD | NC | Positive | 1 | Recovering |
| | | 2 | Leo dormitory, 25 Kaki Bukit Road 3 | PBD | NC | Negative | | |
| 5 | Utracon Structural System Pte Ltd | 10 | 5 Fourth Chin Bee Road, Utracon Corporation Pte Ltd | FCD | NC | Negative | | |
| 6 | Yin Cheng Construction Pte Ltd | 3 | CCK N8C11 | CTQ | NC | Negative | | |
| | | 2 | YISHUN N3C26 | CTQ | CL | Negative | | |
| 7 | Jin Cheng Pte Ltd | 2 | 21 Defu South Street 1, Soilbuild Prefab Innovation Hub | FCD | CL | Negative | | |
| Steel Structural & Metal Works | | | | | | | | |
| 1 | G-Tech Metal Pte Ltd | 10 | 64 Woodlands Industrial Park E9, CCM Industrial | FCD | NC | Positive | 4 | Recovering |
| 2 | Flexi Steel Pte Ltd | 5 | Tuas View Dormitory, 70 Tuas South Avenue 1 | PBD | CL | Negative | | |
| 3 | Soon Li Stainless Steel Works Pte Ltd | 3 | Tuas View Dormitory, 70 Tuas South Avenue 1 | PBD | CL | Negative | | |
| 4 | Asiabuild Metal Engineerigng Pte Ltd | 4 | 32 Sungei Kadut Way | FCD | CL | Negative | | |
| | | 2 | 69 Sennett Ave | PRP | CL | Negative | | |
| 5 | Integrated Aluminium Pte Ltd | 9 | 32 Sungei Kadut Way | FCD | CL | Negative | | |
| 6 | Lai Yew Seng Pte Ltd | 5 | Tuas View Dormitory, 70 Tuas South Avenue 1 | PBD | CL | Negative | | |
| Architectural Works | | | | | | | | |
| 1 | Yin He Construction Pte Ltd | 1 | DAWSON C3 | CTQ | CL | Negative | | |
| | | 9 | BIDADARI C10-C12 | CTQ | NC | Negative | | |
| | | 4 | TAMPINES N6C8-C10 | CTQ | NC | Negative | | |
| | | 1 | SENGKANG WEST WAY Project C | CTQ | CL | Negative | | |
| 2 | Decormark Design Pte Ltd | 8 | Woodlands Lodge II, 190 Woodlands Industrial Park E7 | FCD | NC | Negative | | |
| | | 3 | Harvest @ Woodlands | PRP | CL | Negative | | |
| | | 5 | Woodsvale Condo | PRP | CL | Negative | | |
| 3 | Enlighten Furniture Decoration Pte Ltd | 6 | 3 Loyang Way 6, Enlighten Furniture Decoration Co Pte Ltd | FCD | NC | Negative | | |
| 4 | Ling Feng Construction Pte Ltd | 4 | 9 Woodlands Industrial Park E1 | FCD | NC | Negative | | |
| 5 | Song Furniture Construction & Trading Pte Ltd | 26 | Cochrane Lodge II, 49 Admiralty Road West | PBD | CL | Negative | | |
| | | 3 | Acacia Lodge, 540 Bukit Batok Street 23 | PBD | NC | Negative | | |
| | | 19 | 212 Tagore Lane | TLQ | NC | Positive | 4 | Recovering |
| | | 6 | 174 Tagore Lane | TLQ | NC | Negative | | |

SAFE WORKFORCE

MANPOWER PLANNING

| Manpower Planning For Project Restart Readiness | | | | | | | |
|---|----------------------------|----------------|---------------------------|-----------|----------------|-------------------------|-------------------------|
| S/N | Subcontractor | Trade | Manpower To Restart (Nos) | Dormitory | | | Remarks |
| | | | | Type | Name | Address | |
| A | Essential Works | | | | | | |
| 1 | Teambuild | Essential Work | 19 | TLQ | Senja PCNH | 50, Woodlands Rd 677726 | 2x Swab Test Completed |
| | | Total | 19 | | | | |
| B | Structural Works | | | | | | |
| 1 | Jia Yue Construction | RC | 21 | CTQ | Sengkang N4C31 | HDB Project C | 2 x Swab Test Completed |
| | | RC | 3 | TLQ | Senja PCNH | 50, Woodlands Rd 677726 | 2 x Swab Test Completed |
| | | Total | 24 | | | | |
| C | Architectural Works | | | | | | |
| 1 | Yin He Construction | Wet Trades | 8 | CTQ | Sengkang N4C31 | HDB Project C | 2 x Swab Test Completed |
| | | Total | 8 | | | | |
| D | Electrical Works | | | | | | |
| 1 | United Engineering | Electrical | 1 | TLQ | Senja PCNH | 50, Woodlands Rd 677726 | 2 x Swab Test Completed |
| | | Total | 1 | | | | |
| Grand Total | | | 52 | | | | |

*Initial phase to focus on the critical workforce required for gradual restart.

SAFE WORKSITE

SITE PRE-SCREENING REQUIREMENTS

COVID Safe Induction to Workers in Site



**Senja 12 Storey
Integrated
Development
COVID-Safe Induction Course**

Outline

1. What is Coronavirus/COVID-19
2. How does COVID-19 spread
3. What are the Signs and Symptoms of COVID-19
4. How to protect yourself from COVID-19
5. In-house Rules and Regulations in the Workplace
6. COVID Safe Worksite – Worker Segregation Plan
7. Safe Distancing Measure Permit To Work
8. Emergency Preparedness

SAFE WORKSITE

SAFE DISTANCING



- Physical toolbox talk which has to be carried out daily prior to starting work shall be conducted in smaller group of not more than 10 pax.
- All personnel shall adhere to the SDM 1m at all times.
- Toolbox meeting shall be kept within 10 mins.



SAFE WORKSITE

DAILY MONITORING OF WORKFORCE STATUS

Daily Temperature taking for workers at 8am and 7pm.



| SENIA POINT - WORKERS, DAILY TEMPERATURE TAKING TRACKING | | | | | | | | | | | |
|--|-----------------------|-----------|-----------|------------|-----------------|------|----|-----------------|------|----|---------|
| Sl. No. | Worker Name | ID No. | NRC No. | DOB | Morning 8AM | | | Evening 7PM | | | Remarks |
| | | | | | Temperature (C) | SpO2 | HR | Temperature (C) | SpO2 | HR | |
| 1 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 2 | DOOPATH KARTHIKARANI | 0514 2003 | 8 0010076 | 03/01/2003 | 36.2 | 95 | 75 | 36.5 | 95 | 75 | |
| 3 | PAULANATH VISHNUPATHY | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 4 | PANMAYAL PALANMUTHU | 03112015 | 8 0000000 | 03/11/2015 | 36.5 | 95 | 75 | 36.5 | 95 | 75 | |
| 5 | CHANDRANATH KANDIAN | 03032014 | 8 0000000 | 03/03/2014 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 6 | CHANDRANATH KANDIAN | 03032014 | 8 0000000 | 03/03/2014 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 7 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 8 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 9 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 10 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 11 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 12 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 13 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 14 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 15 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 16 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 17 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 18 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 19 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 20 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 21 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 22 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |
| 23 | PAULANAN SATHISH | 08072018 | 8 0000000 | 02/01/1977 | 36.5 | 95 | 80 | 36.5 | 95 | 80 | |

Google Form to monitor workers health declaration and status



| Name in full (As in NRIC/Fin/Work Permit/Passport) | WP / FIN / NRIC number in full | Company | Date | Time | TEMPERATURE (Temperature > 38.5 not allowed to enter the workplace please refer to the PREVENTED for further instructions) | Cough | Sneezing | Runny Nose | Shortness of Breath | SGWorkPass Color Code | TraceTogether App Installed and Updated | FIN/Work Permit/Passport |
|--|--------------------------------|----------|------------|-------------|--|-------|----------|------------|---------------------|-----------------------|---|--------------------------|
| 1 | | | 11/03/2020 | 10:30:00 AM | 38.4 | No | No | No | No | Green | Yes | Yes |
| 2 | | | 11/03/2020 | 10:30:00 AM | 38.2 | No | No | No | No | Green | Yes | Yes |
| 3 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 4 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 5 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 6 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 7 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 8 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 9 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 10 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 11 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 12 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 13 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 14 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 15 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 16 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 17 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 18 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 19 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 20 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 21 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 22 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |
| 23 | PAULANAN SATHISH | 08072018 | 11/03/2020 | 8:30:00 AM | 38.1 | No | No | No | No | Green | Yes | Yes |

SAFE WORKSITE

DAILY MONITORING OF WORKFORCE STATUS

Google Form to monitor visitors health declaration and status



LOCATION : Senja PCNH – Gate 1



Visitor Health Declaration Form

1 Scan the Visitor's Health Declaration Form QR Code

2 Fill up the Visitor Health Declaration Form Before entering to site

3 Submit form



| Timestamp | Enter your Temperature (e.g. 38.5) Temperature >37.3 is not allowed to enter the workplace. Please inform site PM/SHN/ MC for further instructions. Thank you. | Have you used it using the SafeEntry? | Date of Visit | Time of Visit | Name in full (As in NRIC/Fin/Work Permit/Passport) | WP / FIN / NRIC number in full | Company / Organisation Name | Contact Number | Purpose of Visit | Have you Travelled Overseas in the past 14 days? | Have you received Quarantine / Isolation Order / SHN / MC? |
|---------------------|--|---------------------------------------|---------------|---------------|--|--------------------------------|--|----------------|-------------------------|--|--|
| 18/08/2020 15:02:28 | 38.5 | YES | 18/08/2020 | 08:00:00 | Anthony Saviour | S752177H | Teambuild Engineering and Construction Pte Ltd | 8522991 | Meeting | No | NA Not a WP/SP |
| 18/08/2020 14:04:52 | 38.2 | YES | 18/08/2020 | 14:34:00 | Yong Jun Xiang | S288342H | TBEC | 88514510 | Site work | No | NA Not a WP/SP |
| 17/08/2020 08:08:18 | 38.1 | YES | 17/08/2020 | 07:49:00 | Yong Jun Xiang | S288342H | TBEC | 88514510 | TOL | No | NA Not a WP/SP |
| 17/08/2020 08:08:30 | 38.4 | YES | 17/08/2020 | 08:00:00 | Anthony Saviour | S752177H | TBEC | 8522991 | site work | No | NA Not a WP/SP |
| 17/08/2020 08:08:14 | 38.2 | YES | 17/08/2020 | 07:50:00 | S170149F | S170149F | AUT arena SUPPLY SD | 92267198 | Crane OPERATOR | No | NA |
| 17/08/2020 08:18:18 | 38.2 | YES | 17/08/2020 | 08:10:00 | Han Haizhang | S7178163H | TBEC | 83878488 | Site work | No | NA |
| 17/08/2020 08:28:58 | 38.0 | YES | 17/08/2020 | 08:00:00 | yuanxuezhong | FF789183J | TBEC | 83199924 | site work | No | NA |
| 17/08/2020 08:27:28 | 38.2 | YES | 17/08/2020 | 08:24:00 | Somasundaram Somasundaram | S283244H | Teambuild Engineering & Construction Pte Ltd | 97240116 | Working in site | No | NA |
| 17/08/2020 10:02:02 | 38 | YES | 17/08/2020 | 08:30:00 | Goh Jun Lee | S757849H | Access system technology | 92473256 | Identify security | No | NA |
| 17/08/2020 10:07:33 | 37.2 | YES | 17/08/2020 | 08:30:00 | Chen Ai Cheong | S748842G | AUT | 92267112 | large tool monthly serv | No | NA Not a WP/SP |
| 18/08/2020 08:08:01 | 38.4 | YES | 18/08/2020 | 08:00:00 | Anthony Saviour | S752177H | TBEC | 8522991 | site work | No | NA Not a WP/SP |
| 18/08/2020 08:28:58 | 38.2 | YES | 18/08/2020 | 08:23:00 | Pasuna Pamanathan | S285888H | App Build Construction | 91447561 | Work | No | NA |
| 18/08/2020 08:45:58 | 38 | YES | 18/08/2020 | 08:40:00 | Somasundaram Somasundaram | S283244H | Teambuild Engineering & Construction Pte Ltd | 97240116 | Working in site | No | NA |
| 18/08/2020 10:02:18 | 38.2 | YES | 18/08/2020 | 08:30:00 | YUANXUEZHONG | FF789183J | TBEC | 83199924 | working | No | NA |

| Date of Visit | Time of Visit | Name in full (As in NRIC/Fin/Work Permit/Passport) | WP / FIN / NRIC number in full | Company / Organisation Name | Contact Number | Purpose of Visit | Have you Travelled Overseas in the past 14 days? | Have you received Quarantine / Isolation Order / SHN / MC? | Have you come in close contact with any COVID-19 confirmed cases? |
|---------------|---------------|--|--------------------------------|--------------------------------------|----------------|------------------|--|--|---|
| 17/07/2020 | 08:08:00 | Wong Jun Xiang | | TBEC | 88514510 | Work | No | NA (Not a WP/SP holder) | No |
| 17/07/2020 | 08:00:00 | Han Haizhang | | TBEC | 83878488 | Site work | No | No | No |
| 17/07/0020 | 08:38:00 | Somasundaram Somasundaram | | TBEC | 97240116 | Working at site | No | No | No |
| 17/07/2020 | 08:40:00 | ROXANNE PABONA | | TBEC | 82990840 | Work | No | No | No |
| 17/07/2020 | 08:50:00 | Damian Adrian Rafael | | Teambuild Engineering & Construction | 85986182 | Work | No | No | No |
| 18/07/2020 | 07:35:00 | yuanxuezhong | | TBEC | 83199924 | working | No | No | No |
| 18/07/2020 | 07:50:00 | Han Haizhang | | TBEC | 83878488 | Site work | No | No | No |
| 18/07/2020 | 08:08:00 | Wong Jun Xiang | | TBEC | 88514510 | Work | No | NA (Not a WP/SP holder) | No |
| 18/07/2020 | 08:00:00 | LiGaoyang | | teambuild | 97780498 | site work | No | No | No |
| 18/07/0020 | 11:05:00 | Somasundaram Somasundaram | | TBEC | 97240116 | Working in site | No | No | No |
| 20/07/2020 | 07:45:00 | yuanxuezhong | | TBEC | 83199924 | working | No | No | No |
| 20/07/2020 | 07:45:00 | Yuan Xuezhong | | TBEC | 83199924 | Site work | No | No | No |

SAFE WORKSITE

SPLIT TEAM ARRANGEMENT AND SETTING UP OF OFFICE ZONE

Teams identified into A and B ; segregated access into office



Project: Senja PCNH

| S/N | Full Name | NRIC/FIN | >Work Arrangement | #Shift Number for arrival & departual | #Team Number |
|-----|-----------------------------|-----------|---------------------|---------------------------------------|--------------|
| 1 | KENNY HO MIN KWEE | | Onsite (Shift work) | 8am, 5pm | A |
| 2 | PERUMAL RAMANATHAN | | Onsite (Shift work) | 8am, 5pm | A |
| 3 | HAW YUAN BIN | | Onsite (Shift work) | 8am, 5pm | A |
| 4 | ROXANNE MANALO PABONA | | Onsite (Shift work) | 8am, 5pm | A |
| 5 | YUAN XUE ZHONG | | Onsite (Shift work) | 8am, 5pm | A |
| 6 | ANTHONY SAVIOUR | | Onsite (Shift work) | 8am, 5pm | A |
| 7 | ALAGAPPAN MANIKANDAN | | Onsite (Shift work) | 8am, 5pm | A |
| 8 | RAMALINGAM SINGARAVADIVEL | | Onsite (Shift work) | 8am, 5pm | A |
| 9 | KARUPPIAH MURUGAIAH (PETER) | | Onsite (Shift work) | 8am, 5pm | A |
| 10 | WONG JUN XIANG | | Onsite (Shift work) | 8am, 5pm | A |
| 11 | SOMASUNDARAM SOMASUNDARAM | | Onsite (Shift work) | 830am, 530pm | B |
| 12 | JULIAN KHOO | | Onsite (Shift work) | 830am, 530pm | B |
| 13 | AUNG ZAW LATT | | Onsite (Shift work) | 830am, 530pm | B |
| 14 | RAMALIGAM THANGADURAI | | Onsite (Shift work) | 830am, 530pm | B |
| 15 | HAN HAIZHANG | | Onsite (Shift work) | 830am, 530pm | B |
| 16 | Li Gaoyang | | Onsite (Shift work) | 830am, 530pm | B |
| 17 | RAJUKUMAR SATHISH | | Onsite (Shift work) | 830am, 530pm | B |
| 18 | PADMANABAN GUGAN | | Onsite (Shift work) | 830am, 530pm | B |
| 19 | RAJENDRAN SELVARAJA | | Onsite (Shift work) | 830am, 530pm | B |
| 20 | BOOPATHI KARUNAKARAN | G2802351N | Onsite (Shift work) | 830am, 530pm | B |



| Team | Reporting to Work Site | Break hours | Leaving Work Site |
|--------|------------------------|--------------------|-------------------|
| Team A | 08:00 am | 11:30am to 12:30pm | 5:00pm |
| Team B | 08:30am | 12:30pm to 01:30pm | 5:30pm |





SAFE WORKSITE

WORK ALLOCATION AND COORDINATION

- Armband with color and company name to differentiate individual company
- Green netting to demarcate work area
- Segregated access to working area

| Company | Stair 1 | Stair 2 | Stair 3 | Stair 4 | PM Hoist |
|------------------------|---------|---------|---------|---------|----------|
| Jia Yue (Structural) | | | | | ✓ |
| Yin He (Architectural) | ✓ | ✓ | ✓ | ✓ | |



| SN | Key Trades | Company | Colour code armband with company name |
|----|-------------------|--|---|
| 1 | EHS/General Works | Teambuild Engineering & Construction Pte Ltd |  |
| 2 | Structural | Jia Yue Construction |  |
| 3 | Architectural | Yin He Construction |  |
| 4 | M&E | United Engineering |  |

SAFE WORKSITE

WORK ALLOCATION AND COORDINATION

Permit to Work on Safe Management Measures



| Date of Work 工作日期 | Time of Work Start 开始工作的时间 | Location of Work 工作地点 | Which Zone 哪个区域 | Attached: Namelist of workers working in the Zone and Level with Temperature Record. 附件: 在哪个区域/楼层工作的工人的姓名清单, 温度记录 | Have the workers downloaded the 3 MOM application in their handphones? (e.g. TracTogether, PPMOM, MOM and SCORPASS) 工人是否已在手机中下载了3个MOM应用程序? (例如: TracTogether, PPMOM, MOM和SCORPASS) | Are the workers provided with the necessary PPE? (e.g. Safety Helmet, Safety Shoes, Hand Gloves, Mask, Hand Sanitiser) 是否向工人提供了必要的个人防护设备(安全帽, 安全鞋, 手套, 口罩, 手消毒液) | Is the working area being demarcated and separated 2 meters from other trades working area? 是否将工作区域与其他工种的工作区域分隔2米? | Is proper Safe Distancing Measures being observed in the respective work area? 是否在工作区域观察到适当的安全距离措施? | Have the workers gone through and passed the COVID Safe training? 工人是否经过并通过了COVID安全培训? | Is there adequate ventilation being provided when necessary? 必要时是否提供足够的通风? | Are the workers being briefed on Safe Distancing Measures and gone through Safe Management Measures Induction Course? 是否向工人介绍了安全管理措施并经过了安全管理措施入门课程? | Have the workers been briefed on the Safe Management Measures and confirmed that the safe distancing measures are in place before work can commence. I am also responsible to ensure that the Safe Management Measures are strictly complied. 是否向工人介绍了安全管理措施并确认了安全管理措施到位后才能开始工作。我也负责确保安全管理措施得到严格执行。 | SDO/CSWL Name in Full as in WP/Passport/NRIC 姓名(完整), 身份证/护照/NRIC | SDO/CSWL WP/Passport/NRIC full up in full (Subcontractor) SDO / CSWL WP / (R) / NRIC 完全填写(分包商) | Designation/Role 名称/角色 |
|-------------------|----------------------------|-----------------------|-----------------|---|--|--|--|---|--|--|---|---|--|--|------------------------|
| 25/06/2020 | 14:00:00 | Roof | Zone A | https://drive.google.com/open?id=15GagVYuWdQoneIwRPd7G4tdLJ | Yes | Yes | Yes | Yes | Yes | Yes | Yes | Yes | Savior anthony | Sxxx4251 | SDO |
| 15/07/2020 | 08:00:00 | Level 1 | Zone B | https://drive.google.com/open?id=1yP0kernYst1MdnOCTpHuQweHtD | Yes | Yes | Yes | Yes | Yes | Yes | Yes | Yes | TAN BENG HOCK | G33784830 | Supervisor |
| 16/07/2020 | 09:00:00 | Level 5 | Zone B | https://drive.google.com/open?id=1a2hV11enBert1r1uBMdopYen-T6K7 | Yes | Yes | Yes | Yes | Yes | Yes | Yes | Yes | Tan beng hock | G33784830 | safety supervisor |

SAFE WORKSITE

WORK ALLOCATION AND COORDINATION

Permit to Work on Safe Management Measures

| Date of Work 工作日期 | Time of Work Start 开始工作的时间 | Location of Work 工作地点 | Which Zone 哪个区域 | Attached Namelist of workers working in the Zone and Level with Temperature Record. 随附在带温度记录的区域和级别中工作的工人的姓名清单。 | Have the workers downloaded the SMMOM application in their handphones? (e.g. FaceTogether, FAMOMCare with the necessary PPE? (e.g. SMMOMCare) 工人是否已经下载了 SMMOM 应用程序? (例如 FaceTogether, FAMOMCare 是否向工人提供了必要的个人防护设备? (例如 SMMOMCare 安全盔, 手套, 口罩, 安全鞋等)) | Are the workers provided with the necessary PPE? (e.g. Safety helmet, Safety Shoes, Hand gloves, Mask, hand Sanitizers) 是否向工人提供了必要的个人防护设备? (例如安全盔, 安全鞋, 手套, 口罩, 手消毒液等) | Is the working area being demarcated and separated 2 meters from other trades working area? 是否将工作区域与其他工种的工作区域分隔 2 米? | Is proper Safe Distancing Measures being observed in the respective work area? 在相应的工作区域是否遵守了适当的安全距离措施? | Have the workers gone through and passed the COVID Safe training? 工人是否已经通过了 COVID 安全培训? | Is there adequate ventilation being provided when necessary? 必要时是否提供了足够的通风? | Are the workers being briefed on Safe Distancing Measures and gone through Safe Management Measures Induction Course? 是否向工人介绍了安全距离措施并通过了安全管理措施入门课程? | I have inspected the work area as described above with the SMO/SDO from maincon and am satisfied that the safe distancing measures are in place before work can commence. I am also responsible to ensure that the Safe Management Measures are strictly complied. 我已视察了上述工作区域, 并对此感到满意, 即在开始工作之前已经采取了适当的安全距离措施并遵守了安全管理措施。我同时也是确保严格遵守《安全管理措施》的责任人。 | SDO/CSWL Name in Full as in WP/Passport/NRIC 填写完整 (分包商) | SDO/CSWL WP/Passport/NRIC fill up in full (Subcontractor) SDO / CSWL WP (分包商) | Designation/Role 名称/角色 |
|-------------------|----------------------------|-----------------------|-----------------|---|--|--|--|--|---|---|---|--|---|---|------------------------|
| 25/06/2020 | 14:00:00 | Roof | Zone A | https://drive.google.com/open?id=1GagVv9w6DmstttrRCP6G4JwL_J | Yes | Yes | Yes | Yes | Yes | Yes | Yes | Yes | Seah anthony | Sxxx423i | SDO |
| 15/07/2020 | 08:00:00 | Level 1 | Zone B | https://drive.google.com/open?id=1gWbHmtrRP5lfg41wL_J | Yes | Yes | Yes | Yes | Yes | Yes | Yes | Yes | TAN BENG HOCK | G3378483Q | Supervisor |
| 16/07/2020 | 09:00:00 | Level 5 | Zone B | https://drive.google.com/open?id=1nBbPJ9ZUBMl0kpyee-FOKT | Yes | Yes | Yes | Yes | Yes | Yes | Yes | Yes | Tan beng hock | G3378483Q | safety supervisor |


| Company Name 公司名 | Date of Work 工作日期 | Time of Work Start 开始工作的时间 | Location of Work 工作地点 | Which Zone 哪个区域 | Attached Namelist of workers working in the Zone and Level with Temperature Record. 随附在带温度记录的区域和级别中工作的工人的姓名清单。 |
|---------------------------|-------------------|----------------------------|-----------------------|-----------------|---|
| anthony savior pte ltd | 25/06/2020 | 14:00:00 | Roof | Zone A | https://drive.google.com/open?id=1GagVv9w6DmstttrRCP6G4JwL_J |
| Kim yin(kone) | 15/07/2020 | 08:00:00 | Level 1 | Zone B | https://drive.google.com/open?id=1gWbHmtrRP5lfg41wL_J |
| Kim yin engineering(KONE) | 16/07/2020 | 09:00:00 | Level 5 | Zone B | https://drive.google.com/open?id=1nBbPJ9ZUBMl0kpyee-FOKT |



SAFE WORKSITE

WORK ALLOCATION AND COORDINATION

Plan and demarcate work area to prevent intermixing



SAFE WORKSITE

SAFE DISTANCING MEASURES ON SITE

Signages displayed on site



SAFE WORKSITE

SAFE DISTANCING MEASURES ON SITE

Physical Demarcation in the site.



SAFE WORKSITE

ENFORCEMENT OF SAFE DISTANCING MEASURES ON SITE

Daily inspection by SMO/SDO on SMM using the iSAFE.



TEAMBUILD
CONSTRUCTION BRAND

Page 1 of 3

DAILY SAFETY INSPECTION RECORD

Inspection Date: 24/07/2020 Contract Name : SENJA NURSING HOME
Inspected By: Anthony Saviour, Anthony Saviour, Rajkumar Satish, Ramlingam Singaravadivel,
SOMASUNDARAM SOMASUNDARAM

| S/N | Question | YES | NO | NA | Remarks |
|--|--|-----|----|----|---------|
| General Provisions | | | | | |
| 1. | Open sides of structure are barricaded. | ✓ | | | P1 |
| 2. | Open sides of excavated area are barricaded. | ✓ | | | |
| 3. | Temporary structures are in place | ✓ | | | |
| 4. | PE Design is available | ✓ | | | |
| 5. | Directional signs are prominent to public. | ✓ | | | |
| 6. | Public is prevented to access into the work area. | ✓ | | | |
| 7. | Temporary boundaries with warning signs are put up. | ✓ | | | |
| 8. | Proper access to work place is provided. | ✓ | | | |
| 9. | Overhead shelter at entry / exit is provided. | ✓ | | | |
| 10. | Guarding of unauthorized entry / exit | ✓ | | | |
| 11. | Proper safety rails in place at stairways. | ✓ | | | |
| 12. | Access way is clear. | ✓ | | | |
| 13. | Laddings and access is provided over openings. | ✓ | | | |
| 14. | Lifelines are provided for works at height > 2 meters. | ✓ | | | |
| 15. | Means of working at height is provided. | ✓ | | | |
| 16. | No storage of material / equipment near the edge of building, slope. | ✓ | | | |
| 17. | Warning signs are displayed at boardings and high chain fencing. | ✓ | | | |
| 18. | Safety supervisor is appointed for sub-contractor. | ✓ | | | |
| Electrical Hazards | | | | | |
| 1. | Proper cover for DB is provided and locked. | ✓ | | | |
| 2. | ELCB of 30mA is provided for and used. | ✓ | | | |
| 3. | Wiring is properly hung, not running on the floor. | ✓ | | | |
| 4. | Welding machine and other electrical equipments are earthed. | ✓ | | | |
| 5. | LEW Monthly inspection is done. | ✓ | | | |
| Mechanical Hazards | | | | | |
| 1. | Handtools come with safety guards. | ✓ | | | |
| 2. | Boatworks accompanied with inspection checklist. | ✓ | | | |
| 3. | Boatworks are provided with sturdy fire extinguishers. | ✓ | | | |
| 4. | Maintenance is carried out to tools and equipment. | ✓ | | | |
| Use of Gondola | | | | | |
| 1. | Gondola is approved for use and being inspected regularly. | ✓ | | | |
| 2. | Effective barricades at ground area with warning sign are placed. | ✓ | | | |
| 3. | Safe Working Load of the gondola is / are not exceeded. | ✓ | | | |
| 4. | Gondola overlaid with fine screening debris net. | ✓ | | | |
| Use of Scaffold | | | | | |
| 1. | Scaffold are erected and maintained properly. | ✓ | | | |
| Proper PTW is issued as and where necessary | | | | | |
| 1. | Proper PTW is issued as and where necessary. | ✓ | | | |
| Safe Management Measures | | | | | |
| 1. | Workers / Residents had their daily temperature taken with proper records at least twice a day. | ✓ | | | |
| 2. | Workers / Residents were issued and worn their mask in the workplace / workers' quarters at all times. | ✓ | | | |

| Safe Management Measures | | | | |
|--------------------------|--|---|--|--|
| 1. | Workers / Residents had their daily temperature taken with proper records at least twice a day. | ✓ | | |
| 2. | Workers / Residents were issued and worn their mask in the workplace / workers' quarters at all times. | ✓ | | |

Friday, 24 July 2020



Page 2 of 3

| | | | | |
|----|---|---|--|----|
| 3. | Workers / Residents adhere to safe distancing measures implemented in the workplace / workers' quarters. | ✓ | | P2 |
| 4. | Workers / Residents adhere on the staggered schedule plans / timings for shared facilities, e.g. canteen, toilets, etc. | ✓ | | P3 |
| 5. | Workers / Residents who are on MC or with close contacts of confirmed COVID-19 cases are isolated at all times. And not leave their designated location for any reason unless with approved permission. | ✓ | | P4 |
| 6. | Workers carry a small hand sanitiser with at least 70% alcohol with them at all times before entering the workplace. | ✓ | | |

Verified Date: 24/07/2020 11:46

Verified By: SOMASUNDARAM SOMASUNDARAM

| | |
|----|--|
| P2 | |
| P3 | |
| P4 | |

Friday, 24 July 2020

ENSURE CLEANLINESS OF WORKPLACE PREMISES



DAILY CLEANING/DISINFECTION LOG SHEET

PROJECT: SENIA PCNH

AREA: OFFICE/MEETING ROOM

MONTH: JUN

TO DO LIST:
 1. Tissue Count
 2. Chair Count
 3. Floor Clean
 4. Computer & Keyboard
 5. Trash Bin Empty
 6. Counter Clean

DUTY CLEANER:

K. RATAJOURA


SUPERVISOR IN CHARGE:

VELW

| DATE | DURATION/WORK TIME | | SUPERVISOR CHECK | REMARKS |
|------|--------------------|-----------------|------------------|---------|
| | SAM | 1:00PM - 7:00PM | | |
| 1 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 2 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 3 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 4 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 5 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 6 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 7 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 8 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 9 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 10 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 11 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 12 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 13 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 14 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 15 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 16 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 17 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 18 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 19 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 20 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 21 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 22 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 23 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 24 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 25 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 26 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 27 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 28 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 29 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 30 | <u>K. Rataj</u> | <u>K. Rataj</u> | <u>K. Rataj</u> | |
| 31 | | | | |

SAFE ACCOMMODATION

APPOINTING OF ROOM-IN-CHARGE/CSWL




CTQ-2
ROOM NO: 4

| S/N | NAME | FIN No. | WP No. | Contact No. | Bed No. |
|-----|------------------------------|-----------|------------|-------------|---------|
| 1 | GAZI MAHBUB (Room In Charge) | G2553117K | 0 36366893 | 9087 6323 | 1 |
| 2 | MANIVEL THESAINATHAN | G8668503K | 0 37682853 | 9465 1573 | 2 |
| 3 | LI HAI TAO | G2123610T | 0 75164653 | 9610 9126 | 3 |
| 4 | TANG GUO JUN | G6558041T | 0 73391601 | 83087617 | 4 |
| 5 | SHI LI FANG | G8197855M | 0 72094301 | 98970752 | 5 |
| 6 | YANG SONG HUA | G7133564Q | 0 56193626 | 8656 7891 | 6 |

SAFE ACCOMMODATION

SITE PRE-SCREENING REQUIREMENTS

WhatsApp Group for daily monitoring of Access Code Status




| 18/7/2020 | | | | | |
|---|---------|---------------|-------|-----|---------|
| SUMMARY FOR SUB-CONTRACTORS ACCESS CODE (ON SITE CTQ) | | | | | |
| S/NO | COMPANY | TRADE | GREEN | RED | REMARKS |
| 1 | TBEC | Main Con | 19 | 0 | |
| 2 | Jia Yue | Structural | 1 | 23 | |
| 3 | Yinhe | Architectural | 0 | 8 | |
| 4 | UE | Electrical | 1 | 0 | |

SAFE ACCOMMODATION

COHORTING OF WORKERS IN THE CTQ

Demarcation for CTQ to prevent unauthorised entry & Segregation of Workers in the CTQ.



SAFE ACCOMMODATION

DEMARCATON FOR ISOLATION ROOM AND SICK BAY



SAFE ACCOMMODATION

SEGREGATION OF COMMUNAL FACILITIES

Separation of Isolation Toilets and Common Use Toilets



Common Use Toilet for CTQ Personnel




Hand wash provided at all toilet facilities

SAFE ACCOMMODATION

SEGREGATION OF COMMUNAL FACILITIES

Scheduled Timings for the different rooms for shower facilities are briefed during COVID Safety Induction and displayed at the individual CTQ rooms.



SAFE TRANSPORTATION


SITE PRE-SCREENING REQUIREMENTS

Materials Allocation Plan and Delivery Timing Schedule for different trades subcontractors to prevent intermixing of workers

| Delivery Schedule | | | | | | | | | | | |
|---------------------|------|------|------|------|-------------|------|------|------|------|------|------|
| Timing | 0800 | 0900 | 1000 | 1100 | 1200 | 1300 | 1400 | 1500 | 1600 | 1700 | 1800 |
| Structural Trade | | | | | Lunch Break | | | | | | |
| Architectural Trade | | | | | Lunch Break | | | | | | |

Delivery Control Measure

- TC/Forklift to unload materials
- Driver must stay in cabin
- If driver need to come out:
 - Mask must be worn at all time
 - 2m distancing must be observed
 - Use visitor toilet for toilet break



Material Delivery Allocation Plan

SAFE TRANSPORTATION

SITE PRE-SCREENING REQUIREMENTS

Taking of temperature for drivers coming into site for deliveries by traffic controller.



TEAMBUILD

PROJECT: SINGAPORE
SITE: 191-11-000

VEHICLE LOG/ DISINFECTION


| S/N | DRIVER NAME | MOB. NO. | VEHICLE TYPE | VEHICLE NO. | COMPANY NAME | VEHICLE REGISTRATION NO. | TIME IN | TIME OUT | SIGNATURE |
|-----|-------------|-----------|--------------|-------------|--------------|--------------------------|---------|----------|-------------|
| 1 | Quinn Lee | 9123 4567 | Van | 12345 | ABC Co. | ABC123 | 8:30 | 9:15 | [Signature] |
| 2 | Quinn Lee | 9123 4567 | Van | 12345 | ABC Co. | ABC123 | 9:30 | 10:15 | [Signature] |
| 3 | Quinn Lee | 9123 4567 | Van | 12345 | ABC Co. | ABC123 | 10:30 | 11:15 | [Signature] |
| 4 | Quinn Lee | 9123 4567 | Van | 12345 | ABC Co. | ABC123 | 11:30 | 12:15 | [Signature] |
| 5 | Quinn Lee | 9123 4567 | Van | 12345 | ABC Co. | ABC123 | 13:30 | 14:15 | [Signature] |

APPROVED BY: R. Vithalchandran
SUBMITTED BY: Traffic Controller

CHIEF OF ESTIMATION: [Signature]
S.M.S.

FIT-OUT FACTORY GRADUAL RE-START

SAFE WORKFORCE



| SN | Team | Line | Platform | Remarks |
|----|------|---------|----------|---|
| 1 | ST 1 | 3, 4, 5 | A B C | To be arrange daily based on team identifier colour |
| 2 | ST 2 | 1, 2 | A B C D | |
| 3 | T 3 | 3, 4, 5 | A B C | |
| 4 | T 4 | 3, 4, 5 | A B C | |

- Each Line subdivided into at least 3 platform as per below :-
 - Line 1
Platform A, B, C, D
 - Line 2
Platform B, C, D
 - Line 3
Platform A, B, C
 - Line 4
Platform A, B, C
 - Line 5
Platform A, B, C
- Workers from same team / same colour are assigned to work in each line eg Line 1 Platform A
- No workers from other teams (different color code) are allowed to work within this zone as allocated.
- Only 2 workers is allow to work on each individual PPVC modules in each Line
- All assigned works will be record during the tool box meeting in the meeting. Visual identifiers will issue for all the workers.

FIT-OUT FACTORY GRADUAL RE-START

SAFE WORKSITE



| Working Hour | | | | |
|--------------|-------|-----|-----|-----|
| Team | Entry | | | |
| | 800 | 810 | 820 | 830 |
| ST 1 | | | | |
| ST 2 | | | | |
| T 3 | | | | |
| T 4 | | | | |

| Working Hour | | | | |
|--------------|------|------|------|------|
| Team | Exit | | | |
| | 1700 | 1710 | 1720 | 1730 |
| ST 1 | | | | |
| ST 2 | | | | |
| T 3 | | | | |
| T 4 | | | | |

Line 5 Platform B

Safe Distancing PTW Form
Supervisor/SDO are require to scan the QR Code & submit the **Safe Distancing Measure Permit to Work** before start work

LOCATION : Line 5 – Platform B


Safe Distancing Measure Permit to Work (PTW) Form

- Scan the PTW Form QR Code
- Fill up PTW Form before start work
- Submit form
- Paste PTW form at working area



FIT-OUT FACTORY GRADUAL RE-START

SAFE ACCOMMODATION



DATA ANALYTIC USING CCTV - TRIAL

Thriving in the new normal

POWERED BY



IN COLLABORATION WITH



CONCLUSION

“If we work together as a team, we will be able to ride through this challenging period and emerge stronger!”



THANK YOU.